

# County of Lexington

## Americans with Disabilities Act Transition Plan



## **Americans with Disabilities Act**

The passage of the Americans with Disabilities Act (ADA) of 1990 produced a comprehensive package of civil rights protections for persons with disabilities. The key goals of ADA are to ensure that all people with disabilities have equality of opportunity, economic self-sufficiency, full participation in American life, and independent living. To ensure these goals are met, Title II of the ADA requires state and local governments to make their programs and services accessible to persons with disabilities. [28 CFR §35.149]

In accordance with these requirements the County of Lexington will not discriminate against qualified individuals with disabilities on the basis of disability in services, programs or activities.

Under the ADA, the County of Lexington is required to “make reasonable modifications in policies, practices, or procedures when the modifications are necessary to avoid discrimination on the basis of disability.” The County of Lexington is required to do so in every situation, unless it can demonstrate “that making the modifications would fundamentally alter the nature of the service, program, or activity.” [28 CFR § 35.130(7)]

The “reasonable modification requirement” does not require the County to take any action that would impose an undue financial or administrative burden. The County of Lexington will strive to provide its services, programs and activities in the most accessible manner feasible.

## **General & Administrative Requirements**

Title II of the Americans with Disabilities Act (ADA) identifies specific steps that state and local governments must follow to comply with the ADA. These include:

1. Designate a responsible employee as ADA Coordinator to be responsible for the ADA compliance program;
2. Provide notice to the public of the County’s obligations under Title II to prohibit discrimination on the basis of disability;
3. Establish a Grievance Procedure to respond to complaints regarding accessibility;
4. Prepare a Self- Evaluation of programs, services and activities that may not be accessible to persons with disabilities; and
5. Develop a Transition Plan to provide for the elimination of barriers for disabled persons to access these programs, services and activities.

**ADA Coordinator** - As required by the ADA, public agencies with 50 or more employees must designate a least one responsible employee to coordinate ADA compliance and investigate complaints. The County’s ADA Coordinator can be reached at the following:

County of Lexington Community Development  
Attn: ADA Coordinator  
212 South Lake Drive, Ste 401  
Lexington, South Carolina, 29072  
Phone: 803-785-8121  
Fax: 803-785-8188  
Email: [CDcustomerservice@lex-co.com](mailto:CDcustomerservice@lex-co.com)

**Public Notice** - All public entities, regardless of size, must provide information about the rights and protections of Title II to applicants, participants, beneficiaries, employees, and other interested persons [28 CFR § 35.106]. In order to assist individuals with disabilities who require special services for participation in or access to County programs, services, or meetings, the County posts the follow accommodations notice for all meetings and public hearings:

If special accommodations are needed to participate in this public meeting, please contact the Lexington County Community Development at (803) 785-8121 or [CDCustomerService@lex-co.com](mailto:CDCustomerService@lex-co.com) at least two business days prior to the scheduled meeting date.

**Grievance Procedure** - The County of Lexington is required to adopt and public procedures for resolving grievances arising under Title II of the ADA [28 CFR §35.107 (b)]. The ADA Grievance Policy was adopted by County Council on June 30, 1994. A copy of the ADA Grievance Policy is attached.

**Self- Evaluation** – The County of Lexington has completed its Self-Evaluation by using a system to identify and assess obstacles in its public programs and services, and facilities. The detailed evaluation was accomplished with the use of *ADA Readily Accessible Checklist for Place of Public Accommodations*. The purpose of the checklist is to obtain a comprehensive overview of the complete list of programs and services, and facilities open to the public; to determine which programs and services, and facilities are not in compliance with the ADA guidelines; and to get the highest priority programs and services under review and to remediate as soon as practical. The checklist helped to determine whether the removal of barriers is “readily achievable” and could be decided on a case-by-case basis. If it is determined that some barriers cannot be removed under the “readily achievable” mandate, the list can help identify “alternative methods” enabling persons with disabilities to gain access to services. Barrier removal to programs and services, and facilities are prioritized in order of importance of: 1) access into the facility; 2) access to the goods and services; 3) accessible restrooms; and 4) any other measure improving accessibility. Evaluation of County Facilities was completed April 1995 and a chart is shown as Exhibit A.

**Transition Plan** - The major purpose of a Transition Plan, as it relates to buildings and facilities owned and operated by the County, is to document the barriers to persons with disabilities, that are present in the facilities, and to propose the structural modifications that will be undertaken to provide program accessibility. The County reserves the right to modify barrier removal priorities in order to allow flexibility in accommodating community requests, petitions for reasonable modifications from persons with disabilities, changes in County programs, and funding constraints and opportunities. Due to the County’s efforts to make as many accessibility improvements as possible on a continual basis, some physical improvements listed in the detailed surveys may have been begun, partially completed, or fully completed prior to the adoption of this Transition Plan. The implementation schedules will be updated by the ADA Coordinator to account for progress to provide for inclusion of new information or ADA complaints. It is the goal of this Transition Plan to provide access to the programs, activities and services provided by the County. Interim measures will be explored and implemented in order to provide programmatic access to the public pending the implementation of physical barrier removal projects.



## County of Lexington

### ADA Grievance Policy

The County of Lexington, South Carolina, hereby establishes an internal grievance procedure to provide for equitable and prompt resolution of complaints alleging any violation of U.S. Department of Justice regulations implementing Title II of the Americans with Disabilities Act. Title II states, in part, that “no otherwise qualified disabled individual shall, solely by reason of such disability, be excluded from participation in, or denied the benefits of, or be subjected to discrimination” in programs or activities sponsored by a public entity.

Complaints should be addressed to:

County of Lexington Community Development  
Attn: ADA Coordinator  
212 South Lake Drive, Ste 401  
Lexington, SC 29072  
[CDcustomerservice@lex-co.com](mailto:CDcustomerservice@lex-co.com)

1. Complaints must be filed in writing within thirty (30) days after the complainant becomes aware of the alleged violation, contain the name and address of the person filing it, and briefly describe the circumstances surrounding the alleged violation of the regulations.
2. An investigation, as may be appropriate, shall follow a filing of complaint and shall be conducted by the ADA Coordinator. Such investigation shall be informal but thorough, and shall afford complainant and his/her representative, if any, an opportunity to submit evidence relevant to the complaint.
3. A written determination as to the validity of the complaint and a description of the resolution, if any, shall be issued by the ADA Coordinator and a copy forwarded to the complainant no later than thirty (30) days after its filing.
4. The complainant, in instances where he or she is dissatisfied with the initial resolution, may appeal the decision of the ADA Coordinator to the Chairman of Lexington County Council. Such request should be in writing and submitted within thirty (30) days following receipt of the Coordinator’s decision. Request for reconsideration of the case should be addressed to:

Lexington County Council  
Attn: Chairman  
212 South Lake Drive  
Lexington, SC 29072

5. Files and records of Lexington County related to the complaints filed shall be maintained by the ADA Coordinator.

6. Use of this grievance procedure by a complainant is not a prerequisite to the pursuit of other remedies such as filing of an ADA complaint with the responsible federal department or agency.
7. These rules shall be construed to protect the substantive rights of interested persons to meet appropriate due process standards, and to assure that Lexington County complies with the ADA and implementing regulations.

## **Exhibit A – Self-Evaluation Documentation**

Location	Barriers	Solutions	RA?	Priority	Est. Cost	Comments
Admin Bldg – Basement	212 S. Lake Drive Lexington					
Access to Entrance	No curb ramp to sidewalk. Steps to entry door.		N			*Alternative Methods should be in written policy form.
Entry door	Entry door is hard to open.	Adjust closer.	Y			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/U shaped pull-type hardware.	Y			
	Threshold exceeds ½” and/or is not beveled.	Replace threshold.	Y			
Men’s Restroom	Toilet seat is high.	Install lower toilet seat.	N			21 ¼” actual
	No grab bars at toilet.	Install grab bars.	Y			One vertical bar does not meet current requirement
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32” clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towels dispensers are mounted too high.	Lower dispensers. *Atl method - Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40” above floor.	Install additional mirror at required height.	Y			
Women’s RR	Door is hard to open.	Adjust closer to 5 lbs. opening force.	Y			
	Toilet seat is high.	Install lower toilet seat.	N			21 ½” actual
	No grab bars at toilet.	Install grab bars.	Y			One vertical bar does not meet current requirement
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32”	Y			

		clearance.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towels dispensers are mounted too high.	Lower dispensers. *Alt method - Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signage on elevator control buttons and hoistway door jambs.	Y			Voice recording announcing the floor and its function?
	Water fountain is mounted too high.	Install a paper cup dispenser next to fountain.	Y			
Admin Bldg - 1 <sup>st</sup> Floor	212 S. Lake Drive Lexington					
Access to Entrance	Existing curb ramp is too steep.	Replace steep curb ramp if unsafe. Alt*Paint curb ramp with contrasting color.	Y Y			
Access to Goods /Services	Services are provided at bars or inaccessible levels.	Modify bar to have lower section.	Y			Existing chain to be replaced with latchable door with top at 36" height (treasurer side)
Men's Restroom	Toilet seat is high.	*Alt method – Lower the bowl.	N			21 ½" actual
	No grab bars at toilet.	Install grab bars.	Y			One vertical bar does not meet current requirement
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			Sink does not meet 27" clearance requirement
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			



	Soap and towels dispensers are mounted too high.	Lower dispensers. *Alt method - Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's RR	Door is hard to open.	Adjust closer to 5 lbs. opening force.	Y			
	Toilet seat is high.	Lower toilet.	N			20 ¼" actual
	No grab bars at toilet.	Install grab bars.	Y			One vertical bar does not meet current requirement
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			Sink does not meet 27" clearance requirement
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towels dispensers are mounted too high.	Lower dispensers. *Alt method - Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signage on elevator control buttons and hoistway door jambs.	Y			Voice recording announcing the floor and its function?
	Water fountain is mounted too high.	Install a paper cup dispenser next to fountain.	Y			
Parking	No parking for people with disabilities.	One per eight designated spaces must have 8' aisle.				110 spaces in lower lot & 2 are handicap. See 4.1 For Van platforms see A4.6

Admin Bldg – 2 <sup>nd</sup> Floor	212 S. Lake Drive Lexington					
Access to goods/services	Interior doors lack 32" clearance.	Install wider door.				This is for entrance to public terminal in tax office
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plat/U shaped pull-type door operating hardware.				This is for some doors not all.
	Services are provided at bars or inaccessible levels.	Modify bar to have lower section. *Alt-Serve disable patrons at a table at an accessible level.				*This is for record section & tax office window
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is high.	Install lower toilet seat.	N			22" actual
	No grab bars at toilet.	Install grab bars.	Y			One vertical bar does not meet current requirement
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing- type lever handles.	Y			Sink does not meet 27" clearance requirement
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towels dispensers are mounted too high.	Lower dispensers. *Alt method -Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's RR	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is high.	Install lower toilet seat.	N			22 ½" actual
	No grab bars at toilet.	Install grab bars.	Y			One vertical bar does not meet current requirement
	Toilet partitions limit access to toilet.	Widen toilet stall and install an	Y			

		outswinging door providing 32" clearance.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			Sink does not meet 27" clearance requirement
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towels dispensers are mounted too high.	Lower dispensers. *Alt method - Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signage on elevator control buttons and hoistway door jambs.	Y			Voice recording announcing the floor and its function?
	Water fountain is mounted too high.	Install a paper cup dispenser next to fountain.	Y			
Admin Bldg – 3 <sup>rd</sup> Floor	212 S. Lake Drive Lexington					
Entry door	Door provide less than 32" clearance.	Install wider door.				This is for deed book area only
	Door handle requires grasping, pinching or twisting of wrist	Replace with lever handle or push plate/U shaped pull-type door operating hardware.				
Access to goods/services	Interior door lack 32" clearance.	Install wider door.				For deed book area only
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/U shaped pull-type door operating hardware.				For deed book area only
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is high.	Install lower toilet seat.	N			21" actual
	No grab bars at toilet.	Install grab bars.	Y			One vertical bar does not meet current requirement
	Toilet partitions limit access to toilet.	Widen toilet stall and install an	Y			

		outswinging door providing 32" clearance.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			Sink does not meet 27" clearance requirement
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towels dispensers are mounted too high.	Lower dispensers. *Alt method - Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's RR	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is high.	Install lower toilet seat.	N			21" actual
	No grab bars at toilet.	Install grab bars.	Y			One vertical bar does not meet current requirement
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			Sink does not meet 27" clearance requirement
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towels dispensers are mounted too high.	Lower dispensers. *Alt method - Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signage on elevator control buttons and hoistway door jambs.	Y			
	Water fountain is mounted too high.	Install a paper cup dispenser next to fountain.	Y			

<b>Admin Bldg – 4<sup>th</sup> Floor</b>	212 S. Lake Drive Lexington					
Entry door	Door is hard to open.	Adjust closer.				
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/U shaped pull-type door operating hardware.				All office doors and conference room
Access to goods/services	Interior door lack 32" clearance.	Install wider door.				This is on private offices and storage only
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/U shaped pull-type door operating hardware.				This is on private offices and storage only
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is high.	Alt Method * Lower the bowl.	N			21" actual
	No grab bars at toilet.	Install grab bars.	Y			One vertical bar does not meet current requirement
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing- type lever handles.	Y			Sinks not in compliance with 4.19.2. Must have 29" clearance (RA – Y)
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towels dispensers are mounted too high.	Lower dispensers. *Alt method -Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's RR	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is high.	Alt method *Lower the bowl.	N			21" actual
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32"	Y			

		clearance.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles..	Y			Sinks not in compliance with 4.19.2- Must have 29" clearance (RA-Y)
	Soap and towel dispensers are mounted too high.	Alt method *Maintain bar of soap and towels adjacent to sink.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signage on elevator control buttons and hoistway door jambs.	Y			Activated recording for each floor
	Water fountain is mounted too high.	Install a paper cup dispenser next to fountain.	Y			
<b>Admin Bldg – 5<sup>th</sup> Floor</b>	212 S. Lake Drive Lexington					
Entry Door	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/U shaped pull-type door operating hardware.				
Access to Goods/Services	Interior door(s) lack 32" clearance.	Install wider door.	N			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/U shaped pull-type door operating hardware.				Only Restrooms have push plates
	Aisles are less than 36" wide.	Rearrange goods.	Y			
	Mapping, computer areas, engineering	Put up sign "Employees Only"	Y			
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.	Y			
	Toilet seat is high.		Y			Seat is 21 ½" off floor.
	No grab bars at toilet.	Install grab bars.	Y			Unit has 1 vertical
	Toilet partitions limit access to toilet.	Alt method *Install wider door and jamb to provide 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				Sink not in compliance with 4.19.2. Must have

						clearance of 29". (RA-Y)
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispenser are mounted too high.	Lower dispensers. Alt method *Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.	Y			
	Toilet seat is high.	Alt method *Lower toilet	N			20 3/4" actual.
	No grab bars at toilet.	Install grab bars.	Y			One vertical bar does not meet current requirement
	Toilet partitions limit access to toilet.	Alt method *Move adjacent partition or mount door hinges to wall	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drainlines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Alt method *Maintain bar of soap and towels adjacent to sink.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signage on elevator control buttons and hoistway door jambs.				Alt method *Activated recording for each floor
	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.	Y			
	Water Fountain is mounted too high.	Install a paper cup dispenser next to fountain.	Y			

<b>Admin Bldg – 6<sup>th</sup> Floor</b>	212 S. Lake Drive Lexington					
Entry Door	Door handle requires grasping, pinching or twisting of wrist	Replace with lever handle or push plate/U shaped pull-type door operating hardware				
Access to Goods/Services	Interior door(s) lack 32" clearance	Install wider door.	N			Doors to internal offices in Admin and Finance
	Door handle requires grasping, pinching or twisting of wrist	Replace with lever handle or push plate/U shaped pull-type door operating hardware				
Men's Restroom	Toilet seat is high.		Y			
	No grab bars at toilet	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing- type lever handles.				Remove apron portion at the sinks and insulate as below
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispenser are mounted too high.	Alt method *Maintain bar of soap and towels adjacent to sink.	Y Y			
Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.	Y			
	Toilet seat is high.	Alt method *Lower toilet	N			
	No grab bars at toilet.	Install grab bars.	Y			Existing bars are not compliant
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing- type lever handles.	Y			
	Hot water and drainlines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			



	Soap and towel dispensers are mounted too high.	Lower dispensers. Alt method *Maintain bar of soap and towels adjacent to sink.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signage on elevator control buttons and hoistway door jambs. Install raised signs at all common areas.				
<b>Courthouse – Basement</b>	139. E. Main Street Lexington					
Entry Door	Door is hard to open.	Adjust closer.				
Access to Goods /Services	Door handle requires grasping, pinching, or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Men's Restroom	Door does not provide 32" clearance.		N			
	Toilet seat is low.	Install raised toilet seat.	Y			
	No grab bars at toilet.	Install grab bars.				
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	N			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's Restroom	Door does not provide 32" clearance.		N			
	Toilet seat is low.	Install raised toilet.	Y			
	No grab bars at toilet.	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	N			This room has double sink vanity (not allowed for handicap)
	No sink has grippable faucets.	Replace faucet handles with wing-	Y			

		type lever handles.				
	Soap and towel dispensers are mounted too high.	Lower dispensers.	Y			
<b>Courthouse – Main Floor</b>	139 E. Main Street Lexington					
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
Men's Restroom	Door does not provide 32" clearance.	Widen door.				
	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's Restroom	Door does not provide 32" clearance.	Widen door.				
	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Mirror is mounted higher than 40" above floor.	Lower existing mirror.				
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signage on elevator control buttons and hoistway door jambs.				
	Water Fountain is mounted too high.	Install a paper cup dispenser next to fountain and make it lower.				
<b>Courthouse – 2<sup>nd</sup> Floor</b>	139 E. Main Street Lexington					
Entry Door	Door provides less than 32" clearance.	Install wider door.				No access to North end of this level. Elevator is on South end and access is thru courtroom which is generally locked.
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door				

		operating hardware.				
	Threshold exceeds ½" and/or is not beveled.	Replace threshold.				
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
Interior Features	Signage at the elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signage on elevator control buttons and hoistway door jambs.				
Telephones	Public pay phone is not accessible.					
<b>Public Defender</b>	322A S. Lake Drive Lexington					This building is leased from Rogers Properties and is not subject to ADA
Entry Door	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Threshold exceeds ½" and/or is not beveled.	Replace threshold.				The inside portion exceeds ½".
Access to Goods /Services	Interior door lack 32" clearance.	Install wider door.	N			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Men's Restroom	Door does not provide 32" clearance.	Widen door.				This restroom will have to be rebuilt to be in compliance (space is too small).
	Vestibule is too small.					
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet seat.				
	No grab bars at toilet.	Install grab bars.				
	Toilet partitions limit access to toilet.	Widen toilet stall and install an				

		outswinging door providing 32" clearance.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				
Women's Restroom	Door does not provide 32" clearance.	Widen door.				This restroom will need to be reworked to be in compliance (space is too small).
	Vestibule too small.	Remove inner or outer vestibule door.				
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet.				
	No grab bars at toilet.	Install grab bars.				
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				
	Soap and towel dispensers are mounted too high.	Lower dispensers.				
	Mirror is mounted higher than 40" above floor.	Lower existing mirror.				
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.					No rooms have signage.
	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.				Only has smoke detector.
	Water Fountain is mounted too high.	Install a paper cup dispenser next				

		to fountain.				
Telephones	Public pay telephone is not accessible.					
Parking	No parking for people with disabilities.	Designate 8' space(s) with 5' access aisle(s) [one per eight designated spaces must have 8' aisle] Re-stripe as indicated above.				
	Designated space lacks above grade sign.	Install sign. Ground symbol is insufficient.				
<b>Courthouse Annex</b>	105 S. Lake Drive Lexington					
Access to Entrance	Existing curb ramp is too steep.	Replace steep curb ramp if unsafe. Alt method *Paint curb ramp with contrasting color.				Re-routed Handicap to basement of Courthouse & elevator to main level – to be met by official.
Entry Door	Threshold exceeds ½" and/or is not beveled.	Replace threshold.				
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is low.	Install raised toilet seat.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance. If only one toilet, remove partition completely and install privacy lock.	Y			
	Hot water and drain lines are not insulated	Wrap hot water and drain lines with insulation.	Y			
	Towel dispensers are mounted too high.					
Women's Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door	Y			

		operating hardware.				
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance. If only one toilet, remove partition completely and install privacy lock.	Y			
	Vanity is not allowed- must have open bottom					
	Towel dispensers are mounted too high.	Lower dispensers.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas including restrooms.				
Telephones	Public pay telephone is not accessible.					
<b>Magistrates Office</b>	S. Lake Drive Lexington					No barriers noted.
<b>Microfilm</b>	212 S. Lake Drive Lexington					
Access to Entrance	No curb ramp to sidewalk from parking.	Install curb ramp.	Y			
	Existing curb ramp is too steep to building.	Replace steep curb ramp if unsafe.	Y			Existing ramp is 10° - max. Should be 4° 45'.
Entry Door	Door is hard to open.	Adjust closer. Alt method * Assign employee stationed near door to assist in opening door.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Men's Restroom						This restroom does not meet any of the requirements.
Women's Restroom						This restroom does not meet any of the

						requirements.
<b>Memorial Building</b>	219 E. Main Street Lexington					
Access to Entrance	Step(s) to entry door at front and east side. (HC entry is at west side rear)	Construct ramp.	Y			
Access to Goods /Services	Interior door(s) lack 32" clearance.		N			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Men's Restroom	Door does not provide 32" clearance.	Widen door.	N			Note: HC R/R is unisex and does not meet requirements.
	Toilet seat is low.	Install raised toilet seat.	Y			
	No grab bars at toilet.	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucets handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers. Alt method *Maintain bar of soap and towels adjacent to sinks.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's Restroom	Door does not provide 32" clearance.	Widen door.	N			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			

	No grab bars at toilet.	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucets handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers. Or Alt method *Maintain bar of soap and towels adjacent to sinks.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.	Y			
<b>DSS Trailer No. 1</b>	541 Gibson Road Lexington					Handicap persons are served in main building.
Entry Door	Threshold exceeds 1/2" and/or is not beveled.	Replace threshold.				
Access to Goods /Services	Interior door(s) lack 32" clearance.					Widen door in hallway to gain access to interview offices or conf. room.
	Door handle requires grasping, pinching or twisting of wrist.					
Interior Features						No alarms or smoke detectors in this building.
Telephones	Public pay telephone is not accessible.					
<b>DSS Trailer No. 2</b>	541 Gibson Road Lexington					Handicap persons are served in main building.
Entry Door	Threshold exceeds 1/2" and/or is not beveled.	Replace threshold.				
Interior Features	Fire Alarm does not give visual as					



	well as audible signal.					
Telephones	Public pay telephone is not accessible.					
<b>DSS Main Office</b>	Gibson Road Lexington					
Entry Door	Door is hard to open.	Adjust closer.				
	Threshold exceeds ½" and/or is not beveled.	Create gradual transition with epoxy mortar mix or other materials.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Men's Restroom	Door is hard to open.	Adjust closer.				
	No grab bars at toilet.	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's Restroom	Door is hard to open.	Adjust closer.				
	No grab bars at toilet.	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-	Y			

		type lever handles.				
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Parking	No parking for people with disabilities.	Designate 8' space(s) with 5' access aisle(s) [one per eight designated spaces must have 8' aisle].	Y			
		Re-stripe as indicated above.	Y			
		Install sign. Ground symbol is insufficient.				Signs are too low.
<b>Old Jail Visitor's Area</b>	521 Gibson Road					All Facilities for this are shared with lobby of Traffic Court – Doorway to visitor hall is wide enough but will require door knob replacement.
<b>Traffic Court</b>	521 Gibson Road					This is for Lobby and Courtroom only – Jail portion on separate report
Access to Goods/Services	Door handle requires grasping, pinching or twisting of wrist	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware	Y			
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			Seat should be 17"-19" off floor.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not	Wrap hot water and drain lines	Y			

	insulated.	with insulation.				
Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.	Y			
Parking	Designated space lacks above grade sign.	Install sign. Ground symbol is insufficient.	Y			
<b>Sheriff's Complex</b>	521 Gibson Road					
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's Restroom	Vestibule too small					
	Door is hard to open.	Adjust closer to 5 lbs. opening force.	Y			
	Toilet partitions limit access to toilet.	Wide toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucets handles with wing-	Y			

		type lever handles.				
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Water Fountain is mounted too high.	Install a paper cup dispenser next to fountain.	Y			
Telephones	Public pay telephone is not accessible.	County supplied phone available.	Y			
Parking	Designated space lacks above grade sign.	Install sign. Ground symbol is insufficient.	Y			
<b>Head Start Building No. 1</b>	134 Gibson Court					
Entry Door	Threshold exceeds ½" and/or is not beveled.	Replace threshold.	Y			
Access to Goods/Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plat/"U" shaped pull-type door operating hardware.	Y			
Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plat/"U" shaped pull-type door operating hardware.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			Remove vanity and insulate.
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.	Y			
Telephones	Public pay telephone is not accessible.					
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle)	Y			
	Designated space lacks above grade	Install sign. Ground symbol is	Y			

	sign.	insufficient.				
<b>Head Start Building No. 2</b>	134 Gibson Court					
Entry Door	Threshold exceeds ½" and/or is not beveled.	Replace threshold.	Y			
Access to Goods/Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Men's Restroom	Vestibule is too small.					Not labeled.
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			
	No grab bars at toilet.	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	N			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Women's Restroom	Vestibule is too small.					Not labeled.
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			
	No grab bars at toilet.	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	N			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			

	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.	Y			
Telephones	Public telephone is not accessible.					
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle)				
	Designated space lacks above grade sign.	Install sign. Ground symbol is insufficient.				
<b>Animal Control</b>	321 Ball Park Road					Parking lot is unpaved.
Access to Entrance	No curb ramp to sidewalk.	Install curb ramp.				
Entry Door	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
	Threshold exceeds ½" and/or is not beveled.	Replace threshold. Create gradual transition with epoxy mortar mix or other material.				
Access to Goods / Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
Unisex Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
	Toilet seat is low.	Install raised toilet seat.				
	No grab bars at toilet.	Install grab bars.				
	Toilet partitions limit access to toilet. *See comment.					Remove step in front of shower for proper clearance.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				

	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				
Interior Features	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.				
Telephones	Public pay telephone is not accessible.					No pay phones in area.
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' Access aisles (one per eight designated spaces must have 8' aisle)				Parking lot needs paved area to accommodate handicapped.
<b>Public Works – Road Building</b>	454 Ball Park Road					
Access to Entrance	No curb ramp to sidewalk.	Install curb ramp.				
Entry Door	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
		Create gradual transition with epoxy mortar mix or other material from sidewalk to door.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
Men's Restroom	Toilet seat is low.	Install raised toilet seat.				
	No grab bars at toilet.	Install grab bars.				
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				Add additional sink or remove vanity.
	Soap and towel dispensers are mounted too high.	Lower dispensers.				

	Mirror is mounted higher than 40" above floor.	Lower existing mirror. Install additional mirror at required height.				
Women's Restroom	Door does not provide 32" clearance.					Note: This restroom is too small to get in compliance. *Remove vanity.
	Vestibule too small.					
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
	Toilet seat is low.					
	No grab bars at toilet.					
	Toilet partitions limit access to toilet.					
	No sink has grippable faucets.					
	Soap and towel dispensers are mounted too high.					
	Mirror is mounted higher than 40" above floor.					
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.				No fire alarms in the building.
Telephones	Public pay telephone is not accessible.					
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle.)				
	Designated space lacks above grade sign.	Install sign. Ground symbol is insufficient.				
<b>Public Works – Administration /Engineering</b>	Ball Park Road					
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door				



		operating hardware.				
Men's Restroom	Door does not provide 32" clearance.					
	Vestibule is too small.					
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
	Toilet seat is low.	Install raised toilet seat.				
	No grab bars at toilet.	Install grab bars.				
	Toilet partitions limit access to toilet.					The distance from wall to since is only 25 ½" – This will not meet requirements.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				
	Soap and towel dispensers are mounted too high.	Lower dispensers.				
	Mirror is mounted higher than 40" above floor.	Install additional mirror are required height.				
Women's Restroom	Door does not provide 32" clearance.					
	Vestibule too small.					
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
	Toilet seat is low.					
	No grab bars at toilet.					
	Toilet partitions limit access to toilet.					The distance from wall to sink is only 25 1/2" – This will not meet the requirements.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				

	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.				
	Soap and towel dispensers are mounted too high.	Lower dispensers.				
	Mirror is mounted higher than 40" above floor.	Lower existing mirror.				
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.				
	Fire Alarm does not give visual as well as audible signal.					
Telephones	Public pay telephone is not accessible.					
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle)				Lot not paved.
Magistrate Office District 3	231 West Church Street Batesburg, SC					
Access to Entrance	Existing curb ramp is too steep.	Replace steep curb ramp.	Y			
Entry Door	Threshold exceeds ½" and/or is not beveled.	Replace threshold.				
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				Needs signage.
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			
	No grab bars at toilet.	Install grab bars.	Y			Need one across the back of toilet.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			

Womens' Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			Needs signage.
	Toilet seat is low.	Install raised toilet.	Y			
	No grab bars at toilet.	Install grab bars.				Need bar across the back of toilet.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Interior Features	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with the fire alarm.				Some signs are too high. No detectors are in this building.
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle).				
	Designated space lacks above grade sign.	Install sign. Ground symbol is insufficient.				
<b>Batesburg-Leesville Health Center</b>	229 W. Church Street Batesburg, SC 29006					
Access to Entrance	Existing curb ramp is too steep.	Replace steep curb ramp (too narrow).				
Entry Door		If double leaf doors, replace with one larger/one smaller combination.	Y			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Threshold exceeds ½" and/or is not beveled.	Replace threshold.	Y			
Restroom						Does not meet any of the requirements. (Used by men/women & general

						public. Other restroom turned into storage & lab.
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.				
	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.				No alarm system exists in this building.
	Water Fountain is mounted too high.	Install a paper cup dispenser next to fountain.				
Telephones	Public pay telephone is not accessible.					
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle). Install sign. Ground symbol is insufficient.				
<b>Batesburg- Leesville Leisure Center</b>	227 Highland Avenue Batesburg, SC 29006					
Access to Entrance	Existing curb ramp is too steep.	Replace steep curb ramp. *Alt method: Paint curb ramp with contrasting color.				End of sidewalk is panned out for ramp.
Entry Door	Door is hard to open.	Adjust closer.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				Sink in Leisure Center side is too high.
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			

	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.				
Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is low.	Install raised toilet.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.	Y			
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle). Re-stripe as indicated above.				
<b>Batesburg-Leesville Leisure Center (Senior Citizen Section)</b>	227 Highland Avenue Batesburg, SC					
Entry Door	Door is hard to open.	Adjust closer.				
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"u" shaped pull-type door operating hardware.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"u" shaped pull-type door operating hardware.				
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is low.	Install raised toilet seat.				

	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				Sink is too high 36".
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				
	Soap and towel dispensers are mounted too high.	Lower dispensers. *Alt method: Maintain bar of soap and towels adjacent to sink.				
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.				
Womens' Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is low.	Install raised toilet.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				Sink is too high, 36".
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.				
	Soap and towel dispensers are mounted too high.	Lower dispensers.				
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.				
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.				
<b>Magistrate Office District 4</b>	500 Charlie Rast Road Swansea, SC					
Entry Door	Door is hard to open.	Adjust closer.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware	Y			
Men's Restroom	Door does not provide 32" clearance.	Widen door.	N			
	Door is hard to open.	Adjust closer.				
	Toilet seat is low.	Install raised toilet seat.				

	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				
Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is low.	Install raised toilet.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.				Restrooms, auditorium & courtroom.
	Fire Alarm does not give visual as well as audible signal.					No alarm system in the building.
	Water Fountain is mounted too high.	Install a paper cup dispenser next to fountain.	Y			
Telephones	Public pay telephone is no accessible.	Lower or relocated pay phone.				Access width does not meet requirement of ADA 4.31.2
<b>Swansea Health Center</b>	500 Charlie Rast Road Swansea, SC 29160					
Entry Door	Door handle requires grasping, pinching or twist of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Access to Goods /Services	Door handle requires grasping, pinching or twist of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.				Entrance door only.
<b>Health</b>	112 W. Hospital Drive West Columbia, SC					

<b>Department</b>						
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			
	No sink has grippable faucets.	Replace faucets handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower soap dispensers.	Y			
Women's Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet.	Y			
	No sink has grippable faucets.	Replace faucet set with single lever or push-button type.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Parking		Re-stripe as indicated above (one per eight designated spaces must have 8' aisle)	Y			
<b>Our House</b>	1820 B Augusta Hwy					
Entry Door	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
	Threshold exceeds ½" and/or is not beveled.	Replace threshold. Create gradual transition with epoxy mortar mix or other				



		material.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
	Services (i.e. food, drink) are provided at bars or inaccessible levels.	Alt Method – Serve disable patrons at a table on an accessible level.				Thru open doorway.
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet seat.				
	No grab bars at toilet.	Install 1 grab bars	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower towel dispensers.	Y			
Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs opening force.				
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet.	Y			
	No grab bars at toilet.	Install 1 grab bar.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower towel dispensers.	Y			

Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.				
	Fire Alarm does not give visual as well as audible signal.					No alarms in building.
Telephones	Public pay telephone is not accessible.					
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle)				
		Re-stripe as indicated above.				
		Install sign. Ground symbol is insufficient.				
<b>Alcohol and Drug Abuse Council</b>	134 West Hospital Drive West Columbia, SC					
Access to Entrance		Alt Method-Paint curb ramp with contrasting color.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Unisex Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			
	No grab bars at toilet.	Install grab bars.				No bar at rear of toilet.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are no insulated.	Wrap hot water and drain lines with insulation.	Y			
Interior Features	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.	Y			
Telephones	No public pay telephones in the					

	building.					
Parking	Designated space is too small.	Re-stripe as indicated above. (Designate 8' space with 5' access aisles (one per eight designated spaces must have 8' aisle)	Y			
<b>Mental Health Center</b>	130 Hospital Drive West Columbia					
Entry Door	Threshold exceeds ½" and/or is not beveled.	Replace threshold.	Y			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Men's Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			
	No grab bars at toilet.	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are no insulated.	Wrap hot water and drain lines with insulation.	Y			
	Mirror is mounted higher than 40" above floor.	Lower existing mirror.	Y			
Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.	Y			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32"	Y			

		clearance.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Mirror is mounted higher than 40" above floor.	Lower existing mirror.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.	Y			
	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.	Y			
Telephones	Public pay telephone is not accessible.					None in this area.
Parking	Designated space lacks above grade sign.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle). Re-stripe as indicated above. Install sign. Ground symbol is insufficient.				
<b>Cayce – West Columbia Magistrate</b>	650 Knox Abbott Drive Cayce, SC 29033					
Entry Door	Door is hard to open.	Adjust closer.				
	Threshold exceeds ½" and/or is not beveled.	Replace threshold. Create gradual transition with epoxy mortar mix or other material.				
Access to Goods /Services	Interior doors lack 32" clearance.	Install wider door.	N			Some – not all.
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			Some – not all.
Men's Restroom	Door does not provide 32" clearance.	Widen door.	N			

	Vestibule is too small.	Remove inner or outer vestibule door.	Y			
	Toilet seat is low.	Install raised toilets seat.	Y			
	No grab bars at toilet.	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Wide toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's Restroom	Door does not provide 32" clearance.	Widen door.	N			
	Toilet seat is low.	Install raised toilet.	Y			
	No grab bars at toilet.	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Widen toilet and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.	Y			
	Water fountain is mounted too high.	Install paper cup dispenser next to fountain.	Y			
Parking	Designated space is too small.	Re-stripe as indicated above.				Only 1 space exists.
<b>Irmo Magistrate</b>	108 Harbison Blvd. Columbia, SC 29212					
Entry Door	Door is hard to open.	Adjust closer.				

Men's Restroom	Door is hard to open.	Adjust closer.				
	Toilet seat is low.	Install raised toilet seat.				
	One grab bar at toilet.	Install grab bars.				
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.				Door to stall does not have 32" clearance.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				
	Soap and towel dispensers are mounted too high.	Lower towel dispenser.				
Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is low.	Install raised toilet.	Y			
	One grab bar at toilet.	Install grab bars.	Y			
	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			The access door is not 32" clearance.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower towel dispenser.	Y			
	Mirror is mounted higher than 40" above floor.	Lower existing mirror or Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying room or spaces is not raised.	Install raised signs at all common areas.				
	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.				
Telephones	Public pay telephone is not					

	accessible.					
Parking		Install sign. Ground symbol is insufficient.				Need 1 additional space.
<b>Mental Health Center</b>	1611 Augusta Road West Columbia, SC					
Access to Entrance						Note: Ramp entrance need repair to maintain smooth transition from driveway.
Entry Door	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
	Threshold exceeds ½" and/or is not beveled.	Create gradual transition with epoxy mortar mix or other material.				
	Interior doors lack 32" clearance.		N			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
Unisex Restroom	Door does not provide 32" clearance.		N			
	Vestibule is too small.		N			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	N			
	Threshold exceeds ½" and/or is not beveled.		N			
	Toilet seat is low.		N			
	No grab bars at toilet.		N			
	Toilet partitions limit access to toilet.		N			
	No sink has grippable faucets.		N			
	Hot water and drain lines are not insulated.		N			
	Saop and towel dispensers are		N			

	mounted too high.					
	Mirror is mounted higher than 40" above floor.		N			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.					All floors are at different levels and have thresholds that exceed ½".
	Fire Alarm does not give visual as well as audible signal.					
	Water Fountain is mounted too high.					
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle).				
<b>Museum</b>	Fox Street Lexington, SC					No part of this facility meets any of the requirements.
<b>Recreation &amp; Aging Commission (West End)</b>	500 Charlie Rast Road Swansea, SC					
Entry Door	Door is hard to open.	Adjust closer.				
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet partitions limit access to toilet.					Door is only 31" wide.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				Vanity has to be removed to provide for access 4.19.2
	Soap and towel dispensers are mounted too high.	Lower dispensers. *Alt. method – Maintain bar of soap and towels adjacent to sink.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			



Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.					Vanity not allowed. See Men's room comments.
	Soap and towel dispensers are mounted too high.	Lower dispensers. *Alt method- Maintain bar of soap and towels adjacent to sink.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas (restrooms).				
	Fire Alarm does not give visual as well as audible signal.					No Fire Alarms or smoke detectors.
Telephone	Public pay telephone is not accessible.					
<b>Aging &amp; Recreation Commission</b>	563 South Lake Drive Lexington, SC 29072					
Entry Door	Threshold exceeds ½" and/or is not beveled.	Create gradual transition with epoxy mortar mix or other material.	Y			
Men's Restroom	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace entire faucet set with single lever or push-button type.	Y			Sinks are 2 ½" higher than max. required.
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				

	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's Restroom	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			
	No sink has grippable faucets.	Replace faucet set with single lever or push-button type.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.	Y			
Parking	Designated space is too small.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle). Re-stripe as indicated above.				
	Designated space lacks above grade sign.	Install sign. Ground symbol is insufficient.				
<b>West Columbia /Cayce Senior Center</b>	754 B Avenue					
Entry Door		If double leaf doors, replace with one larger/one smaller combination.	Y			
Men's Restroom	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers. *Alt method – Maintain bar of soap and towels adjacent to sink.				
	Mirror is mounted higher than 40"	Install additional mirror at required				

	above floor.	height.				
Women's Restroom	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers. *Alt method – Maintain bar of soap and towels adjacent to sink.				
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying room or spaces is not raised.	Install raised signs at all common areas (restrooms).				
	Fire Alarm does not give visual as well as audible signal.					None exist.
Telephones	Public pay telephone is not accessible.					
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisle (one per eight designated spaces must have 8' aisle). Install sign. Ground symbol is insufficient.				
<b>Recreation and Aging Comm. (Senior Section)</b>	108 Park Road Lexington, SC					
Entry Door	Door is hard to open.	Adjust closer.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.				
Men's Restroom	Toilet seat is low.	Install raised toilet.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				Sink too high 36", should be max 34".

	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.				
Women's Restroom	Toilet seat is low.	Install raised toilet.				
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				Sink is too high 36", should be max 34".
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.				
	Mirror is mounted higher than 40" above floor.	Replace existing mirror with larger mirror, bottom edge at 40" above floor. Install additional mirror at required height.				
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.				
<b>Recreation and Aging Comm. (Gym Section)</b>	108 Park Road Lexington, SC					
Access to Entrance	Existing curb ramp is too steep.	*Alternative method – Paint ramp with contrasting color.				
Entry Door	Door is hard to open.	Adjust closer.				
	Threshold exceeds ½" and/or is not beveled.	Create gradual transition with epoxy mortar mix or other material.				
Men's Restroom	Door his hard to open.	Adjust closer to 5 lbs. opening force.				
	Threshold exceeds ½" and/or is not beveled.	Create gradual transition with epoxy mortar mix or other material, or grinding marble to beveled edge.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			

	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			Sink is 35", code says 34 max 4.19.2.
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.				
Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Threshold exceeds ½" and/or is not beveled.	Created gradual transition with epoxy mortar mix or other material, or grinding marble to beveled edge.	Y			
	Toilet seat is low.	Installed raised toilet.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				Sink is 35", code says 34" max 4.19.2.
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.	Y			
<b>South Congaree Senior Center</b>	113 W. Berry Road West Columbia, SC 29172					Building is owned by South Congaree
Entry Door	Threshold exceeds ½" and/or is not beveled.	Replace threshold.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.				
Men's Restroom	Vestibule is too small.	*Alternative method – remove partition.				
	Door handle requires grasping,	Replace with lever handles or push	Y			

	pinching or twisting of wrist.	plate/"U" shaped pull-type door operating hardware.				
	Toilet seat is low.	Install raised toilet seat.				
	Toilet partitions limit access to toilet.	If only one toilet, remove partition completely and install private lock.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Mirror is mounted higher than 40" above floor.	Lower existing mirror.				
Women's Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet.				
	Toilet partitions limit access to toilet.	If one toilet, remove partition completely and install privacy lock on restroom door.	Y			
	No sink has grippable faucets.	Replace faucet handle with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Towel dispensers are mounted too high.	Lower dispensers.	Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior Features		Install raised signs at all common areas (restrooms)				No alarm system exists. No fountain exists.
Telephones	Public pay telephone is not accessible.					
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle). Install sign. Ground symbol is				

		insufficient.				
<b>Shealy House</b>	223 East Main Street Lexington, SC					Tornado took care of this one.
Entry Door	Threshold exceeds ½" and/or is not beveled.	Replace threshold.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.				
Men's Restroom	Door does not provide 32" clearance.	Widen door.				Not HC designed. Does not meet requirements.
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.				
	Toilet seat is low.	Install raised toilet seat.				
	No grab bars at toilet.	Install grab bars.				
	Toilet partitions limit access to toilet.					
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.				
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				
Women's Restroom	Door does not provide 32" clearance.	Widen door.				
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.				
	Threshold exceeds ½" and/or is not beveled.	Replace threshold (or remove).				
	Toilet seat is low.	Install raised toilet.	Y			
	No grab bars at toilet.	Install grab bars.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Mirror is mounted higher than 40"	Install additional mirror at required	Y			

	above floor.	height.				
Interior Features		Install raised signs at all common areas (restrooms).				
	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.				
	Water Fountain is mounted too high.	Install a paper cup dispenser next to fountain.				
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle).				4.1.6 says you must put up signage indicating accessible entrance location.
<b>Welcome Home Children</b>	4788 Platt Springs Road Lexington, SC					This facility is locker at all times and is occupied by custodian 24 hrs/day 7 days/week.
Telephones	Public pay telephone is not accessible.					
Parking	No parking for people with disabilities.					
<b>Community Mental Health Center</b>	138 West Hospital Drive West Columbia, SC					
Entry Door	Door is hard to open.	Adjust closer.				
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.	Y			
Men's Restroom	Vestibule is too small.		N			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			
	No grab bars at toilet.	Install grab bars.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-	Y			



		type lever handles.				
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Women's Restroom	Vestibule too small.		N			
	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet.	Y			
	No grab bars at toilet.	Install grab bars.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Interior Features		Install raised signs at all common areas.	Y			
	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.	Y			No pull station.
Telephones	Public pay telephone is not accessible.					None in this area.
Parking	Designated space lacks above grade sign.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle). Re-stripe as indicated above. Install sign. Ground symbol is insufficient.	Y Y Y			
<b>Library / Chapin Rec. Complex</b>	107 Columbia Ave Chapin, SC 29036					
Access to Goods /Services						Some doorways have ¾" high thresholds caused by different floor elevations.
	Door handle requires grasping,	Replace with lever handles or push	Y			

	pinching or twisting of wrist.	plate/"U" shaped pull-type door operating hardware.				
	Aisles are less than 36" wide.		Y			Some aisles in library do not comply.
	Goods are located on high shelves.	*Alternative Method – Provide customer assistance by retrieving goods.	Y			
Men's Restroom	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			Work in progress 8-22-95.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers. *Alternative method – Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Women's Restroom	Toilet partitions limit access to toilet.	Widen toilet stall and install an outswinging door providing 32" clearance.	Y			Work in progress 8-22-95.
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers. *Alternative method- Maintain bar of soap and towels adjacent to sink.	Y Y			
	Mirror is mounted higher than 40" above floor.	Install additional mirror at required height.	Y			
Interior features	Signage at elevators and other	Install raised signage on elevator	Y			

	permanent signage identifying room or spaces is not raised.	control buttons and hoistway door jambs.				
	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.	Y			
<b>Irmo Chapin Rec. Commission (Gym Section)</b>	200 Leisure Lane Columbia, SC 29210					
Entry Door	Door is hard to open.	Adjust closer.				
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
Interior Features	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.				Does not have any smoke detectors or warning devices.
	Water Fountain is mounted too high.	Install a paper cup dispenser next to fountain.				
<b>Irmo Chapin Rec. Commission (Senior Section)</b>	200 Leisure Lane Columbia, SC 29210					
Entry Door	Door is hard to open.	Adjust closer.				
Men's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is low.	Install raised toilet seat.				
Women's Restroom	Door is hard to open.	Adjust closer to 5 lbs. opening force.				
	Toilet seat is low.	Install raised toilet.				
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.				

<b>Landfill</b>	498 Landfill Road Lexington, SC					
Access to Entrance	No curb ramp to sidewalk.	Install curb ramp. Construct ramp at entry door by scale control.				
Entry Door	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.				
	Threshold exceeds ½" and/or is not beveled.	Replace threshold. Create gradual transition with epoxy mortar mix or other material.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.				
Men's Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.				
	Toilet seat is low.	Install raised toilet seat.				
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.				
Women's Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.				
	Toilet seat is low.	Install raised toilet.				
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.				
Interior Features						No alarms in building. No water fountain in the building.
Telephones	Public pay telephone is not accessible.					
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated				

		spaces must have 8' aisle).				
<b>Circulating Library</b>	203 Amory Street Batesburg, SC 29006					
Access to Entrance	Existing curb ramp is too steep.	Replace steep curb ramp if unsafe.				
Entry Door	Door provides less than 32" clearance.	If double leaf doors, replace with one larger/one smaller combination.				
	Door is hard to open.	Adjust closer.				
Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.				
	Goods are located on high shelves.	*Alternative method – Provide customer assistance by retrieving goods.				
Men's Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet seat.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
Women's Restroom	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handles or push plate/"U" shaped pull-type door operating hardware.	Y			
	Toilet seat is low.	Install raised toilet.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
Interior Features	Signage at elevators and other permanent signage identifying rooms or spaces is not raised.	Install raised signs at all common areas.				
	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.				
	Water Fountain is mounted too high.	Install a paper cup dispenser next to fountain.				

Telephone	Public pay telephone is not accessible.					
Parking	No parking for people with disabilities.	Designate 8' spaces with 5' access aisles (one per eight designated spaces must have 8' aisle). Re-stripe as indicated above. Install sign. Ground symbol is insufficient.				
<b>Cayce-West Columbia Branch Library</b>	1500 Augusta Road West Columbia, SC 29169					
Entry Door	Door is hard to open.	Adjust closer.				
Access to Goods /Services	Goods are located on high shelves.	*Alternative Method – Provide customer assistance by retrieving goods.				
Men's Restroom	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Women's Restroom	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Interior Features	Signage at elevators and other permanent signage identifying room or spaces is not raised.	Install raised signage on elevator control buttons and hoistway door jambs.				
Parking	Designated space lacks above grade sign.	Install sign. Ground symbol is insufficient.				
<b>Irmo Library</b>	108 Harbison Boulevard Columbia, SC 29212					
Entry Door	Door is hard to open.	Adjust closer.				
	Threshold exceeds ½" and/or is not beveled.	Replace threshold.				

Access to Goods /Services	Door handle requires grasping, pinching or twisting of wrist.	Replace with lever handle or push plate/"U" shaped pull-type door operating hardware.	Y			
	Aisles are less than 36" wide.	Rearrange goods.	Y			
	Goods are located on high shelves.	Lower or reposition shelves. *Alternative method – Provide customer assistance by retrieving goods.				
Men's Restroom	Toilet seat is low.	Install raised toilet seat.	Y			
	One grab bar at toilet.	Install grab bars.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers.				
Women's Restroom	Toilet seat is low.	Install raised toilet.	Y			
	One grab bar at toilet.	Install grab bars.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines at sink are not insulated.	Wrap hot water and drain lines with insulation.	Y			
	Soap and towel dispensers are mounted too high.	Lower dispensers.	Y			
Interior Features	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.				
Telephone	Public pay telephone is not accessible.					
Parking						See magistrate report for 108 Harbison.
<b>Swansea Library</b>	240 South Mammoth Swansea, SC 29160					

Access to Goods /Services	Aisles are less than 36" wide.	Rearrange goods. *Alternative method – Provide customer assistance by retrieving goods.	Y			
	Goods are located on high shelves.	*Alternative method – Provide customer assistance by retrieving goods.				
Unisex Restroom	Door does not provide 32" clearance.					
	Toilet seat is low.	Install raised toilet seat.	Y			
	No grab bars at toilet.	Install grab bars.	Y			
	No sink has grippable faucets.	Replace faucet handles with wing-type lever handles.	Y			
	Hot water and drain lines are not insulated.	Wrap hot water and drain lines with insulation.	Y			
Interior Features	Fire Alarm does not give visual as well as audible signal.	Install flashing light to activate with fire alarm.				
Telephones	Public pay telephone is not accessible.					



